

# REPORT # 03/09/101 803

- Aug 17 2010

M.T.O. Meeting

Marked and staked out Boudreau ditch from Wayen Clouthier Drive wa  
To M.T.O. ditch east side of Boudrea  
There a drawing with Report.

Met with Steve Boland Renfrew Co.  
Paul Sarrazin with Tranfield Service  
Doug Ryan M.T.O. AT west end of  
Dunlop Cres. Explained the problem  
measured about 20 meters of Hwy  
Shoulder to reroute water from  
entrance. Went to east Entrance  
Dunlop Cres. Explained problem?  
Ryan will look more into solve  
Problem. Checked out Boudreau Rd.  
Entrance and ditch, showed Dc

2009 10/11/2010 4. 19/09/10

Ryran where we place ditch, depth,  
-and 4" stone Doug Ryran No Problem  
having ditch put in Talked about  
Kenny Rd entrance, Paul Sarazin  
also says entrance is to narrow,  
Doug Ryran will look into Widen  
the entrance if money is there.

Doug Ryran

Maintenance Co-ordinator  
Northeastern Region  
Contracts Office North Bay Area

Ministry of Transportation  
447 McKeown Avenue  
North Bay, On P1B-9S9

Tel: 705-497-5417

Fax: 705-497-6800

Email [doug.ryran2@ontario.ca](mailto:doug.ryran2@ontario.ca)

Wilfred Sumner  
Aug 31 - 2010

Bellwires have to be located

Boudreau Rd.

Driveway

Centre of Rd.

50 sign 50 KM

Mail Boxes

Centre of Rd.

4" stone

15" depth

proper toe stroke  
10" depth

Centre of Rd.

Boudreau Rd. Entrance  
Pitch from

Hury Entrance to Wain  
Aug 31 - 2010

